

VALMEX® pacific VALMEX® atlantic VALMEX® wind

Loose dirt and dust to be brushed off with a soft brush when material is dry. Hoovering or beating is also possible as long as the material is not subjected to high mechanical stress.

Small stains can be removed with lukewarm water (30° C) if necessary use a mild detergent (max. 5% soap solution) remove staining carefully. Rinse thoroughly until all remaining soap and detergent is washed out completely.

Allow to fully air dry.

The cover should never be rolled up and packed away when wet!

Under **no circumstance** should the material be treated with high pressure washers or cleaning processes that use abrasion, for example hard brushes, do not use chemical substances or put the material in a washing machine.



Mehler Technologies GmbH

Rheinstrasse 11 · D-41836 Hückelhoven

Edelzeller Strasse 44 · D-36043 Fulda

Tel. +49 (0) 2433 459 0 · Fax +49 (0) 2433 459 151

info@mehler-technologies.com · www.mehler-technologies.com